



Application Specifications:030 Strippable Booth Coatings

Chemco's 030 Water-Based Strippable Booth Coatings are formulated for spray application. They may also be brushed or rolled on if necessary.

030 is a ready-to-use paint related coating. Reduction should not be needed, however, if desired, distilled water may be used.

When applying, use spray application when possible. Best results have been achieved using: 1.) air-less spray system, 2.) a pressure feed with separate atomizing air equipment, or 3.) air-assisted air-less spray equipment. In most cases, 030 can be applied using the same spray-gun tip used in your current spray application. If you spray extremely thin coatings in your normal processes, you may need to apply the 030 using a tip with a larger orifice. Contact Chemco if you feel that an alternative tip may be needed. If electrostatic equipment is used we suggest disconnecting the power unit so that no electrical charge is applied to the coating.

030 Coatings are NOT RECOMMENDED FOR USE IN EXTERIOR APPLICATIONS OR IN ENVIRONMENTS WITH EXPOSURE TO ELEVATED TEMPERATURES. If you need a strippable coating for an environment with elevated temperatures, please call us at 800-323-0431 and inquire about our Hi-Temp strippable coatings. Elevated temperatures are defined as those over 95° F.

The surface on which the 030 is applied should be dry and free from all dirt, oil, grease and especially old overspray. A concentration of old overspray can cause the 030 to adhere to the surface thus preventing stripping. Oil or grease will prevent cohesion and cause the dried film to "self strip."

We recommend an application of 8-10 wet mils which will dry to a minimum of 3 dry mils. Under normal circumstances 3 dry mils will produce a tough elastic film which is easily peeled even with high accumulations of overspray. It is suggested a thicker coating be applied where additional tear resistance is required such as floors, grates, etc.

In order to remove the coating, simply score through the accumulated overspray and the 030 to the booth wall. Lift the coating along the score line until a sheet large enough to grasp with both hands is available. Then, simply peel the coating from the surface. When applied correctly, the 030 will peel off the booth wall in large sheets.

The sheets of 030 with the accumulated overspray should be disposed of as the overspray itself would be disposed. Always dispose of overspray related material in accordance with all federal, state, and local regulations.

030 should be stored between 65-70° F. If frozen, some 030 coatings could be damaged and rendered useless. Contact Chemco regarding our line of 030 Freezable strippable coatings at 800-323-0431.

For more information or to check out our entire product catalog, visit us at www.chemcomfg.com or call us toll-free at 800-323-0431

FOR INDUSTRIAL USE ONLY 03/18/08